

Controller Repair Service Center Board Exchange Pricing

(Effective May 2, 2025)

Count on it.

| Product | Current Part # | Description | F25 List Price | Core Fee |
|----------------------|----------------|--|-------------------|----------|
| Network 8000 | R91-1280 | Timing Mechanism | \$443.00 | \$155.05 |
| | R35-6166 | Power Supply | \$255.00 | \$89.25 |
| | R89-8100 | Triac Board | \$114.00 | \$39.90 |
| Network VP Satellite | R102-3497-4.0 | Timing Mechanism - Version 4.03(comes with current firmware) | \$444.00 | \$155.40 |
| | R102-9738 | Timing Mechanism - Version VPE-add note | \$444.00 | \$155.40 |
| | R118-5487 | Timing Mechanism-Sensor Capatible-add note | \$444.00 | \$155.40 |
| | R118-2737 | Verticle Power Dist Board | \$259.00 | \$90.65 |
| | R102-8576 | Power Distribution Board-ROHS | \$212.00 | \$74.20 |
| | R102-2782 | Power Distribution Board | \$212.00 | \$74.20 |
| | R102-3015 | Pump Module | \$165.00 | \$57.75 |
| | R102-8577 | Pump Module-Same as R102-3015 LEAD FREE | \$165.00 | \$57.75 |
| | R102-3125 | Radio Adaptor Board | \$165.00 | \$57.75 |
| | R102-8277 | Radio Adaptor Board-Same as R102-3125 LEAD FREE | \$165.00 | \$57.75 |
| | R102-2549 | Output Module | \$155.00 | \$54.25 |
| | R102-8242 | Output Module-Same as R102-2549 LEAD FREE | \$155.00 | \$54.25 |
| | R118-6161 | Standard Modem-2WIRE | \$214.00 | \$74.90 |
| | R363-4638 | Maxon Data Radio | \$353.00 | \$123.55 |
| Lynx Smart Satellite | R118-6363 | LSS Timing Mechanism | \$654.00 | \$228.90 |
| | R118-3045 | LSS Dist Board Pcb Assy | \$174.00 | \$60.90 |
| | R118-6369 | LSS Pump Common Assy - Inc Cover replaced R118-3041 | \$990.00 | \$346.50 |
| | R118-6370 | LSS Relay Output Board Assy-Inc Cover-Replaces R118-3043 | \$1,098.00 | \$384.30 |
| | R118-3705 | LSS Modem Wire Pcb Assy | \$206.00 | \$72.10 |
| | R118-3339 | LSS Radio Int Pcb Assy | \$174.00 | \$60.90 |
| | R118-6133 | LSS Radio Module Assy (replaces R118-3442)-M7 | \$2,060.00 | \$721.00 |
| | R118-3047 | LSS Terminal Board with LvI 4 Surge | \$129.00 | \$45.15 |
| | R118-1524 | LSS Surge Comm PCBA Assy, ROHS | \$129.00 | \$45.15 |
| OSMAC | RNLN3491A | Triac Board | \$175.00 | \$61.25 |
| | R91-1303 | Surge Board | \$277.00 | \$96.95 |
| | R91-1305 | Surge Board | \$193.00 | \$67.55 |
| | R91-1307 | Sp. Comm | \$104.00 | \$36.40 |

| Product | Current Part # | Description | F25 List Price | Core Fee |
|-------------------|----------------|---|-------------------|----------|
| E-Series | R102-0320 | Pump & Common PCB | \$148.00 | \$51.80 |
| | R102-8242 | 8-Output Module PCB(same as R102-2549) | \$155.00 | \$54.25 |
| | R102-2549 | 8-Output Module PCB | \$155.00 | \$54.25 |
| | R102-0318 | Output Distribution PCB | \$140.00 | \$49.00 |
| | R89-9804 | Surge Projection W/SW & Gas Pills - Non ROHS | \$200.00 | \$70.00 |
| | R102-8390 | Surge Protection W/SW & Gas Pills(same as R89-9804) | \$200.00 | \$70.00 |
| | R89-9896 | Earth Group PCB | \$93.00 | \$32.55 |
| | R102-8393 | Earth Group PCB-Same as R89-9896 LEAD FREE | \$93.00 | \$32.55 |
| | R89-9894 | 24 VAC BAR PCB | \$93.00 | \$32.55 |
| | R102-8392 | 24 VAC BAR PCB-Same as R89-9894 LEAD FREE | \$93.00 | \$32.55 |
| | R102-0382 | Power Transformer | \$295.00 | \$103.25 |
| Osmac G3 | R118-2986 | G3 ТМ | \$1,542.00 | \$539.70 |
| | R102-0318 | Output Distribution PCB | \$140.00 | \$49.00 |
| | R102-0320 | Pump & Common PCB | \$148.00 | \$51.80 |
| | R102-8242 | 8-Output Module PCB(same as R102-2549) | \$155.00 | \$54.25 |
| Network LTC 1.1 | R91-1303 | Surge Board | \$277.00 | \$96.95 |
| | R91-1305 | Surge Board | \$193.00 | \$67.55 |
| | R91-1307 | Sp. Comm | \$104.00 | \$36.40 |
| Network LTC 2.0 | R89-6977 | Back Plane | \$218.00 | \$76.30 |
| | R89-7170 | Output Module | \$112.00 | \$39.20 |
| | R89-7171 | Pump Common Module | \$107.00 | \$37.45 |
| Network LTC 4.0 | R102-0238 | Timing Mechanism | \$403.00 | \$141.05 |
| | R89-8521 | Surge Board (Surge & Switch) | \$222.00 | \$77.70 |
| | R102-8080 | Surge Board (Surge & Switch)Same as R89-8521 | \$222.00 | \$77.70 |
| | R102-8086 | Pump & Comm. Surge-Same as (R89-8589 LEAD FREE) | \$129.00 | \$45.15 |
| | R89-8589 | Pump & Comm. Surge | \$129.00 | \$45.15 |
| | R118-1524 | Pump & Comm. Surge (Same as R102-8086 also LEAD FREE) | \$129.00 | \$45.15 |
| | R102-0681 | 8-Output Module | \$168.00 | \$58.80 |
| | R102-0682 | Pump Common Module | \$129.00 | \$45.15 |
| | R102-8082 | Pump Common Module-Lead Free | \$129.00 | \$45.15 |
| | R102-8084 | Output Module | \$171.00 | \$59.85 |
| | R102-3125 | Radio Adaptor Board | \$165.00 | \$57.75 |
| | R102-8277 | Radio Adaptor Board-Same as R102-3125 LEAD FREE | \$165.00 | \$57.75 |
| | R102-0382 | Power Transformer | \$295.00 | \$103.25 |
| | R363-4638 | Maxon Data Radio | \$353.00 | \$123.55 |
| | R102-0612 | Distribution Board | \$186.00 | \$65.10 |
| | R102-8078 | Distribution Board-Same as R102-0612 LEAD FREE | \$186.00 | \$65.10 |
| | R118-6161 | Standard Modem | \$214.00 | \$74.90 |
| Network LTC Pro | R118-4837 | VP-LTCP Timing Mechanism | \$481.00 | \$168.35 |
| | R118-2737 | Verticle Power Dist Board | \$259.00 | \$90.65 |
| | R118-6161 | Standard Modem | \$214.00 | \$74.90 |
| GDC 2 Wire System | R118-0582 | 2 Wire Decoder Mother Board-(With Display) | \$409.00 | \$143.15 |
| | R118-0584 | 2 Wire Decoder Daughter Board (works with MB-R118-0582) | \$211.00 | \$73.85 |

| Product | Current Part # | Description | F25 List Price | Core Fee |
|-------------------|----------------|--|-------------------|----------|
| Lynx Smart Hub | R118-4728 | Lynch Smart Hub Timing Mechanism | \$744.00 | \$260.40 |
| | R118-7187 | Lynx Smart Hub Surge Output Board, DC | \$91.00 | \$31.85 |
| | R118-0582 | 2 Wire Decoder Mother Board, DC-(works W/R118-0584 DB) | \$409.00 | \$143.15 |
| | R118-0584 | 2 Wire Decoder Daughter Board, DC (works w/R118-0582 MB) | \$211.00 | \$73.85 |
| | R118-7096 | 2 Wire Decoder Mother Board, DC-(works W/R118-7097SK DB) | \$504.00 | \$176.40 |
| | R118-7097 | 2 Wire Decoder Daughter Board, DC (works w/R118-7096SK MB) | \$252.00 | \$88.20 |
| | R118-6133 | LSH Radio Module Assy (replaces R118-3442) | \$2,060.00 | \$721.00 |
| TDC-2 Wire System | R118-3106 | 2 Wire Decoder TM Assy | \$1,146.00 | \$401.10 |
| | R118-0582 | 2 Wire Decoder Mother Board, DC-(works W/R118-0584 DB) | \$409.00 | \$143.15 |
| | R118-0584 | 2 Wire Decoder Daughter Board, DC (works w/R118-0582 MB) | \$211.00 | \$73.85 |
| MISC | R363-6166 | Plastic Cabinet Lock Assy | \$8.00 | \$2.80 |



Controller Repair Service Center

Repair and Return Pricing ***Core Required in Advance

(Effective May 2, 2025)

| Product | Part # | Description | F25 List | Core Fee |
|----------------------|--------------|---|----------|----------|
| Osmac G3 | R363-7402 | Antenna, 450-470 MHZ, BNC, 6" Straight | \$27.00 | |
| Network 8K | R35-6326 | Pump Module | \$126.00 | |
| | R35-7899 | Surge Board | \$190.00 | |
| | R35-8646 | Modem Board | \$222.00 | |
| | R35-8502 | Valve Board | \$185.00 | \$64.75 |
| Network VP Satellite | R102-9124 | LTCP/VP Conv Power Dist Board -Same as 118-7024 ROHS | \$220.00 | |
| | R102-0104 | Standard Modem-2WIRE | \$214.00 | |
| | R102-8568 | Standard Modem-Same as R102-0104 LEAD FREE-2WIRE | \$214.00 | |
| | R102-0106 | Universal Modem-New Version-Radio | \$252.00 | |
| | R102-8570 | Universal Modem-New Version-Same as R102-0106 & replaces R89-8453 | \$252.00 | \$88.20 |
| Lynx Smart Satellite | R118-3128 | LSS Dist Expan Board Pcb Assy | \$57.00 | |
| | R118-6035 | LSS Pump Common Terminal Board with Lvl 3 Surge | \$84.00 | |
| | R118-6034 | LSS Pump Common Terminal Board with Lvl 4 Surge | \$109.00 | |
| | R102-0645 | LSS Power Supply Assy | \$382.00 | |
| Network LTC 1.0 | R91-1593 | Timing Mechanism without Term-1.1 Firmware | \$572.00 | |
| | R91-1593-2.5 | Timing Mechanism without Term-2.5 Firmware | \$572.00 | \$200.20 |
| | R91-0537 | Timing Mechanism with Term-1.1 Firmware | \$484.00 | \$169.40 |
| | R91-0537-2.5 | Timing Mechanism with Term-2.5 Firmware | \$484.00 | |
| | R91-0777 | Modem Board | \$495.00 | |
| Network LTC 2.0 | R89-7169 | Timing Mechanism | \$463.00 | |
| | R89-7519 | Standard Modem | \$235.00 | \$82.25 |
| Network LTC 4.0 | R102-0104 | Standard Modem | \$214.00 | \$74.90 |
| | R102-8568 | Standard Modem-Same as R102-0104 LEAD FREE | \$214.00 | \$74.90 |
| Network LTC Pro | R102-0104 | Standard Modem | \$214.00 | \$74.90 |
| | R102-8568 | Standard Modem-Same as R102-0104 LEAD FREE | \$214.00 | \$74.90 |
| GDC 2-Wire | R102-5918 | 2 Wire Decoder Stand Alone TM Assy | \$486.00 | \$170.10 |
| | R102-7693 | 2 Wire Decoder Daughter Board (Old P/N R102-4339) | \$263.00 | \$92.05 |
| | R102-7696 | 2 Wire Decoder Mother Board Big Cap(Old P/N R102-5044) | \$249.00 | \$87.15 |
| VT4 | R35-6220 | Timing Mechanism | \$550.00 | \$192.50 |
| OSMAC | RNLN3485 | Decoder Board | \$535.00 | \$187.25 |
| E-Series | R102-0187 | Narrow Band E-Osmac Decoder | \$533.00 | \$186.55 |
| | R102-2012 | Narrow Band RDR Decoder | \$533.00 | \$186.55 |
| | R102-0645 | Power Supply Assy | \$382.00 | |
| Misc | RFIU | All FIU PCB's | \$939.00 | \$328.65 |

**Subject to Repair Chargeback

Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.

Count on it.