



Count on it.

Controller Repair Service Center Board Exchange Pricing

(Effective Nov 1, 2025)

Product	Current Part #	Description	F26 List Price	Core Fee
Network 8000	R91-1280	Timing Mechanism	\$452.00	\$158.20
	R35-6166	Power Supply	\$260.00	\$91.00
	R89-8100	Triac Board	\$116.00	\$40.60
Network VP Satellite	R102-3497-4.0	Timing Mechanism - Version 4.03(comes with current firmware)	\$453.00	\$158.55
	R102-9738	Timing Mechanism - Version VPE-add note	\$453.00	\$158.55
	R118-5487	Timing Mechanism-Sensor Capatible-add note	\$453.00	\$158.55
	R118-2737	Verticle Power Dist Board	\$264.00	\$92.40
	R102-8576	Power Distribution Board-ROHS	\$216.00	\$75.60
	R102-2782	Power Distribution Board	\$216.00	\$75.60
	R102-3015	Pump Module	\$168.00	\$58.80
	R102-8577	Pump Module-Same as R102-3015 LEAD FREE	\$168.00	\$58.80
	R102-3125	Radio Adaptor Board	\$168.00	\$58.80
	R102-8277	Radio Adaptor Board-Same as R102-3125 LEAD FREE	\$168.00	\$58.80
	R118-4306	Radio Interface Board-DR+C109	\$152.00	\$53.20
	R102-2549	Output Module	\$158.00	\$55.30
	R102-8242	Output Module-Same as R102-2549 LEAD FREE	\$158.00	\$55.30
	R102-9124	LTCP/VP Conv Power Dist Board -Same as 118-7024 ROHS	\$224.00	\$78.40
	R118-7024	LTCP/VP Conv Power Dist Board - ROHS	\$224.00	\$78.40
	R102-0104	Standard Modem-2WIRE	\$218.00	\$76.30
	R102-8568	Standard Modem-Same as R102-0104 LEAD FREE-2WIRE	\$218.00	\$76.30
	R118-6161	Standard Modem-2WIRE	\$218.00	\$76.30
	R363-4638	Maxon Data Radio	\$360.00	\$126.00



Count on it.

Controller Repair Service Center Board Exchange Pricing

(Effective Nov 1, 2025)

Product	Current Part #	Description	F26 List Price	Core Fee
Lynx Smart Satellite	R118-6363	LSS Timing Mechanism	\$667.00	\$233.45
	R118-3045	LSS Dist Board Pcb Assy	\$177.00	\$61.95
	R118-6369	LSS Pump Common Assy - Inc Cover	\$1,010.00	\$353.50
	R118-6370	LSS Relay Output Board Assy-Inc Cover	\$1,120.00	\$392.00
	R118-3705	LSS Modem Wire Pcb Assy	\$210.00	\$73.50
	R118-3339	LSS Radio Int Pcb Assy	\$177.00	\$61.95
	R118-6133	LSS Radio Module Assy (replaces R118-3442)-M7	\$2,101.00	\$735.35
	R118-3047	LSS Terminal Board with Lvl 4 Surge	\$132.00	\$46.20
	R118-3128	LSS Dist Expan Board Pcb Assy	\$58.00	\$20.30
	R118-6035	LSS Pump Common Terminal Board with Lvl 3 Surge	\$86.00	\$30.10
	R118-6034	LSS Pump Common Terminal Board with Lvl 4 Surge	\$111.00	\$38.85
	R102-0645	LSS Power Supply Assy	\$390.00	\$136.50
	R118-1524	LSS Surge Comm PCBA Assy, ROHS	\$132.00	\$46.20
OSMAC	RNLN3491A	Triac Board	\$179.00	\$62.65
	R91-1303	Surge Board	\$283.00	\$99.05
	R91-1305	Surge Board	\$197.00	\$68.95
	R91-1307	Sp. Comm	\$106.00	\$37.10



Count on it.

Controller Repair Service Center Board Exchange Pricing

(Effective Nov 1, 2025)

Product	Current Part #	Description	F26 List Price	Core Fee
E-Series	R102-0187	Narrow Band E-Osmac Decoder	\$544.00	\$190.40
	R102-2012	Narrow Band RDR Decoder	\$544.00	\$190.40
	R102-0645	Power Supply Assy	\$390.00	\$136.50
	R102-0320	Pump & Common PCB	\$151.00	\$52.85
	R102-8242	8-Output Module PCB(same as R102-2549)	\$158.00	\$55.30
	R102-2549	8-Output Module PCB	\$158.00	\$55.30
	R102-0318	Output Distribution PCB	\$143.00	\$50.05
	R89-9804	Surge Projection W/SW & Gas Pills - Non ROHS	\$204.00	\$71.40
	R102-8390	Surge Protection W/SW & Gas Pills(same as R89-9804)	\$204.00	\$71.40
	R89-9896	Earth Group PCB	\$95.00	\$33.25
	R102-8393	Earth Group PCB-Same as R89-9896 LEAD FREE	\$95.00	\$33.25
	R89-9894	24 VAC BAR PCB	\$95.00	\$33.25
	R102-8392	24 VAC BAR PCB-Same as R89-9894 LEAD FREE	\$95.00	\$33.25
	R102-0382	Power Transformer	\$301.00	\$105.35
Osmac G3	R118-2986	G3 TM	\$1,573.00	\$550.55
	R102-0318	Output Distribution PCB	\$143.00	\$50.05
	R102-0320	Pump & Common PCB	\$151.00	\$52.85
	R363-7402	Antenna, 450-470 MHZ, BNC, 6" Straight	\$28.00	\$9.80
	R102-8242	8-Output Module PCB(same as R102-2549)	\$158.00	\$55.30
Network LTC 1.1	R91-1303	Surge Board	\$283.00	\$99.05
	R91-1305	Surge Board	\$197.00	\$68.95
	R91-1307	Sp. Comm	\$106.00	\$37.10
Network LTC 2.0	R89-6977	Back Plane	\$222.00	\$77.70
	R89-7170	Output Module	\$114.00	\$39.90
	R89-7171	Pump Common Module	\$109.00	\$38.15



Count on it.

Controller Repair Service Center Board Exchange Pricing

(Effective Nov 1, 2025)

Product	Current Part #	Description	F26 List Price	Core Fee
Network LTC 4.0	R102-0238	Timing Mechanism	\$411.00	\$143.85
	R89-8521	Surge Board (Surge & Switch)	\$226.00	\$79.10
	R102-8080	Surge Board (Surge & Switch)Same as R89-8521	\$226.00	\$79.10
	R102-8086	Pump & Comm. Surge-Same as (R89-8589 LEAD FREE)	\$132.00	\$46.20
	R89-8589	Pump & Comm. Surge	\$132.00	\$46.20
	R118-1524	Pump & Comm. Surge (Same as R102-8086 also LEAD FREE)	\$132.00	\$46.20
	R102-0681	8-Output Module	\$171.00	\$59.85
	R102-0682	Pump Common Module	\$132.00	\$46.20
	R102-8082	Pump Common Module-Lead Free	\$132.00	\$46.20
	R102-8084	Output Module	\$174.00	\$60.90
	R102-3125	Radio Adaptor Board	\$168.00	\$58.80
	R102-8277	Radio Adaptor Board-Same as R102-3125 LEAD FREE	\$168.00	\$58.80
	R102-0382	Power Transformer	\$301.00	\$105.35
	R363-4638	Maxon Data Radio	\$360.00	\$126.00
	R102-0612	Distribution Board	\$190.00	\$66.50
	R102-8078	Distribution Board-Same as R102-0612 LEAD FREE	\$190.00	\$66.50
	R102-0104	Standard Modem	\$218.00	\$76.30
	R102-8568	Standard Modem-Same as R102-0104 LEAD FREE	\$218.00	\$76.30
R118-6161	Standard Modem	\$218.00	\$76.30	
Network LTC Pro	R118-4837	VP-LTCP Timing Mechanism	\$491.00	\$171.85
	R118-2737	Verticle Power Dist Board	\$264.00	\$92.40
	R118-4306	Radio Interface Board-DR	\$152.00	\$53.20
	R102-0104	Standard Modem	\$218.00	\$76.30
	R102-8568	Standard Modem-Same as R102-0104 LEAD FREE	\$218.00	\$76.30
	R118-6161	Standard Modem	\$218.00	\$76.30



Count on it.

Controller Repair Service Center Board Exchange Pricing

(Effective Nov 1, 2025)

Product	Current Part #	Description	F26 List Price	Core Fee
GDC 2 Wire System	R118-0582	2 Wire Decoder Mother Board-(With Display)	\$417.00	\$145.95
	R118-0584	2 Wire Decoder Daughter Board (works with MB-R118-0582)	\$215.00	\$75.25
Lynx Smart Hub	R118-4728	Lynx Smart Hub Timing Mechanism	\$759.00	\$265.65
	R118-7187	Lynx Smart Hub Surge Output Board, DC	\$93.00	\$32.55
	R118-0582	2 Wire Decoder Mother Board, DC-(works W/R118-0584 DB)	\$417.00	\$145.95
	R118-0584	2 Wire Decoder Daughter Board, DC (works w/R118-0582 MB)	\$215.00	\$75.25
	R118-7096	2 Wire Decoder Mother Board, DC-(works W/R118-7097SK DB)	\$514.00	\$179.90
	R118-7097	2 Wire Decoder Daughter Board, DC (works w/R118-7096SK MB)	\$257.00	\$89.95
	R118-6133	LSH Radio Module Assy (replaces R118-3442)	\$2,101.00	\$735.35
TDC-2 Wire System	R118-3106	2 Wire Decoder TM Assy	\$1,169.00	\$409.15
	R118-0582	2 Wire Decoder Mother Board, DC-(works W/R118-0584 DB)	\$417.00	\$145.95
	R118-0584	2 Wire Decoder Daughter Board, DC (works w/R118-0582 MB)	\$215.00	\$75.25
FIU	R102-3125	Radio Adaptor Board-Maxon	\$168.00	\$58.80
	R102-8277	Radio Adaptor Board-Same as R102-3125 LEAD FREE-Maxon	\$168.00	\$58.80
	R118-4306	Radio Interface Board-DR	\$152.00	\$53.20
	R118-4307	Radio Interface Board-FIU Only	\$108.00	\$37.80
MISC	R363-6166	Plastic Cabinet Lock Assy	\$8.00	\$2.80



Count on it.

Controller Repair Service Center

Repair and Return Pricing ***Core Required in Advance***

(Effective Nov 1, 2025)

Product	Part #	Description	F26 List	Core Fee
Network 8K	R35-6326	Pump Module	\$131.00	\$45.85
	R35-7899	Surge Board	\$198.00	\$69.30
	R35-8646	Modem Board	\$231.00	\$80.85
	R35-8502	Valve Board	\$192.00	\$67.20
Network VP Satellite	R102-0106	Universal Modem-New Version-Radio	\$262.00	\$91.70
	R102-8570	Universal Modem-New Version-Same as R102-0106 & replaces R89-8453	\$262.00	\$91.70
Network LTC 1.0	R91-1593	Timing Mechanism without Term-1.1 Firmware	\$595.00	\$208.25
	R91-1593-2.5	Timing Mechanism without Term-2.5 Firmware	\$595.00	\$208.25
	R91-0537	Timing Mechanism with Term-1.1 Firmware	\$503.00	\$176.05
	R91-0537-2.5	Timing Mechanism with Term-2.5 Firmware	\$503.00	\$176.05
	R91-0777	Modem Board	\$515.00	\$180.25
Network LTC 2.0	R89-7169	Timing Mechanism	\$482.00	\$168.70
	R89-7519	Standard Modem	\$244.00	\$85.40
GDC 2-Wire	R102-5918	2 Wire Decoder Stand Alone TM Assy	\$505.00	\$176.75
	R102-7693	2 Wire Decoder Daughter Board (Old P/N R102-4339)	\$274.00	\$95.90
	R102-7696	2 Wire Decoder Mother Board Big Cap.-(Old P/N R102-5044)	\$259.00	\$90.65
VT4	R35-6220	Timing Mechanism	\$572.00	\$200.20
OSMAC	RNLN3485	Decoder Board	\$556.00	\$194.60
Misc	RFIU	All FIU PCB's	\$977.00	\$341.95

****Subject to Repair Chargeback**

Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.