

## E-Series™ Osmac®

**E-Osmac** is easy to service, troubleshoot and maintain. Economical because you buy only what you need and can expand as your site conditions change.



LEAD  
FREE

**E-Series Osmac Narrow Band Decoder**

**SKU: R102-0187 – \*Repair & Return Only**



**E-Series Osmac 8-Output Module PCB**

**SKU: R102-2549**



**E-Series Osmac Pump & Common PCB**

**SKU: R102-0320**



LEAD  
FREE

**E-Series Osmac 8-Output Module PCB**

**SKU: R102-8242**



LEAD  
FREE

**E-Series Osmac Narrow Band RDR Decoder**

**SKU: R102-2012 – \*Repair & Return Only**



**E-Series Osmac Output Distribution PCB**

**SKU: R102-0318**



**E-Series Osmac Power Supply**


**SKU: R102-0645 – \*Repair & Return Only**

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.




**TORO**

## E-Series™ Osmac®



E-Series Osmac Surge Protection with  
SW & Gas Pills - Non ROHS

**SKU: R89-9804**



LEAD  
FREE

E-Series Osmac Surge Protection with  
SW & Gas Pills

**SKU: R102-8390**



E-Series Osmac Earth Ground PCB

**SKU: R89-9896**



LEAD  
FREE


E-Series Osmac Earth Ground PCB

**SKU: R102-8393**



E-Series Osmac 24 VAC BAR PCB

**SKU: R89-9894**



LEAD  
FREE

E-Series Osmac 24 VAC BAR PCB

**SKU: R102-8392**

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.



## Osmac<sup>®</sup>



Osmac Decoder Board

**SKU: RNLN3485** – *\*Repair & Return Only*



Osmac Triac Board

**SKU: RNLN3491A** – *\*Repair & Return Only*



Network LTC 1.1 Surge Board

**SKU: R91-1303**



Network LTC 1.1 Surge Board

**SKU: R91-1305**



Network LTC 1.1 Sp. Comm

**SKU: R91-1307** – *\*Repair & Return Only*

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.




## Osmac® G3



Osmac G3 Timing Mechanism

**SKU: R118-2986**




Osmac Output Distribution PCB

**SKU: R102-0318**



Pump & Common PCB

**SKU: R102-0320**



8-Output Module PCB

**SKU: R102-8242** (Same as R102-2549)

**LEAD  
FREE**



Osmac G3 Antenna, 450-470 MHZ, BNC, 6" Straight

**SKU: R363-7402**

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.



## GDC 2-Wire

**GDC System** uses innovative technology to provide an irrigation solution to value oriented customers who also want a safe, reliable and energy efficient system.

Using a **2-wire** path to communicate to buried control units, the system eliminates the costs associated with traditional valve wire bundles and provides a solution that is vandal resistant, easy to install and easy to expand.



**GDC 2-Wire Decoder Mother Board Big Cap**

**SKU: R102-7696** – *\*Repair & Return Only*



**GDC 2-Wire Decoder Daughter Board**

**SKU: R102-7693** – *\*Repair & Return Only*



**GDC 2-Wire Decoder Mother Board**

**SKU: R118-0582**

**LEAD  
FREE**



**GDC 2-Wire Decoder Daughter Board**

**SKU: R118-0584**

**LEAD  
FREE**



**GDC 2-Wire Decoder Standalone TM Assembly**

**SKU: R102-5918** – *\*Repair & Return Only*

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.



## Network VP®

**Network VP** combines modular flexibility, ease of use and increased control in a single controller.



**Network VP Timing Mechanism - Version 4.0  
with current firmware**

**SKU: R102-3497-4.0**



**Network VP Timing Mechanism - Version VPE**

**SKU: R102-9738**



**Network VP Timing Mechanism - Sensor Compatible**

**SKU: R118-5487**



**LEAD  
FREE**

**Network VP Vertical Power Distribution Board**

**SKU: R118-2737**



**LEAD  
FREE**

**Network VP Power Distribution Board - ROHS**

**SKU: R102-8576**



**Network VP Power Distribution Board**

**SKU: R102-2782**



**Network VP Pump Module**

**SKU: R102-3015**

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.



## Network VP®

With individual station runtime programmed to the second and station-based flow management, **Network VP** provides the most water efficient capabilities for irrigating.



### Network VP Pump Module

**SKU: R102-8577** (Same as R102-3015)



### Network VP/LTC™ 4.0 Radio Adapter Board

**SKU: R102-3125**



### Network VP/LTC 4.0 Radio Adapter Board

**SKU: R102-8277** (Same as R102-3125)



### Network VP Output Module

**SKU: R102-2549**



### Network VP Output Module

**SKU: R02-8242** (Same as R102-2549) – *\*Repair & Return Only*



### LTC/VP Conversion Power Distribution Board

**SKU: R102-9124**



### Network VP Maxon Data Radio

**SKU: R363-4638**

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.



## Lynx® Smart Hub

**Lynx Smart Hub** provides flexibility and unique solutions to golf courses. It is the controller that adds the security, programmability, and sensing capabilities of a trusted Toro® satellite to the benefits and simplicity of the Lynx GDC 2-Wire Control System.



**Lynx Smart Hub Timing Mechanism**

**SKU: R118-4728**



LEAD  
FREE

**Lynx Smart Hub 2-Wire Decoder Mother Board, DC**

**SKU: R118-0582**



LEAD  
FREE

**Lynx Smart Hub 2-Wire Decoder Daughter Board, DC**

**SKU: R118-0584**



LEAD  
FREE

**Lynx Smart Hub 2-Wire Decoder Mother Board, DC**

**SKU: R118-7096**



LEAD  
FREE

**Lynx Smart Hub 2-Wire Decoder Daughter Board, DC**

**SKU: R118-7097**



LEAD  
FREE

**Lynx Smart Hub Output Board, DC**

**SKU: R118-7187**



**Lynx Smart Hub Radio Module Assembly**

**SKU: R118-6133** (Replaces R118-3442)

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.





## Lynx® Smart Satellite

**Lynx Smart Satellite** is designed to improve performance and reliability and is fully compatible with Network VP® and Network 8000 systems as an addition or replacement.



LEAD  
FREE

Lynx Smart Satellite Pump Common Surge PCBA Assembly

**SKU: R118-1524**



LEAD  
FREE

Lynx Smart Satellite Distribution Board

PCB Assembly

**SKU: R118-3045**



LEAD  
FREE

Lynx Smart Satellite Distribution Expansion Board

PCB Assembly

**SKU: R118-3128** – *\*Repair & Return Only*



LEAD  
FREE

Lynx Smart Satellite Radio Int PCB Assembly

**SKU: R118-3339**



LEAD  
FREE

Lynx Smart Satellite Pump Common Terminal Board

with Lvl 4 Surge - *\*Repair & Return Only*

**SKU: R118-6034**



Lynx Smart Satellite Timing Mechanism

**SKU: R118-6363**

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.



## Lynx® Smart Satellite




LEAD  
FREE

### Lynx Smart Satellite Relay Output Boards Assembly

*(Includes plastic covers)*


**SKU: R118-6370**



LEAD  
FREE

### Lynx Smart Satellite Pump Common Relay Assembly

**SKU: R118-6369** *(Replaces R118-3041) – \*Repair & Return Only*



LEAD  
FREE


### Lynx Smart Satellite Terminal Board with Lvl 4 Surge

**SKU: R118-3047**



### Lynx Smart Satellite Power Supply Assembly

**SKU: R102-0645**



LEAD  
FREE

### Lynx Smart Satellite Modem Wire PCB Assembly

**SKU: R118-3705**



### Lynx Smart Satellite Radio Module Assembly

**SKU: R118-6133**



LEAD  
FREE

### Lynx Smart Satellite Pump Common Terminal Board with Lvl 3 Surge

**SKU: R118-6035** – *\*Repair & Return Only*

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.



## Network LTC™ 1.1

Genuine **LTC Upgrade Kits** facilitate a step-by-step upgrade to the Lynx® Central Control System. Upgraded satellites remain compatible with other LTC Plus satellites and with the SitePro® Central Control System until you are ready to convert to Lynx Central Control.



**Network LTC Timing Mechanism with Term 1.1 Firmware**  
**SKU: R91-0537** – *\*Repair & Return Only*



**Network LTC Timing Mechanism with Term 2.5 Firmware**  
**SKU: R91-0537-2.5**



**Network LTC Timing Mechanism 1.1 Firmware without Terminal Block**  
**SKU: R91-1593**



**Network LTC Timing Mechanism 2.5 Firmware without Terminal Block**  
**SKU: R91-1593-2.5** – *\*Repair & Return Only*



**Network LTC 1.1 Surge Board**  
**SKU: R91-1303**

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.




## Network LTC™ 1.1



Network LTC 1.1 Surge Board

**SKU: R91-1305**



Network LTC 1.1 Sp. Comm

**SKU: R91-1307**



Network LTC Modem Board

**SKU: R91-0777 – \*Repair & Return Only**

## Network LTC 2.0



Network LTC 2.0 Timing Mechanism

**SKU: R89-7169 – \*Repair & Return Only**



Network LTC 2.0 Back Plane

**SKU: R89-6977**



Network LTC 2.0 Output Module

**SKU: R89-7170**



Network LTC 2.0 Pump Common Module

**SKU: R89-7171**

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.



## Network LTC™ 4.0



Network LTC 4.0/Plus 8-Output Module

**SKU: R102-0681**



Network LTC 4.0/Plus Pump & Common Module

**SKU: R102-0682**



Network LTC 4.0/Plus Pump & Common Module

LEAD  
FREE

**SKU: R102-8082**



Network LTC 4.0/Plus Distribution Board

**SKU: R102-0612**



Network LTC 4.0/Plus Distribution Board

LEAD  
FREE

**SKU: R102-8078** (Same as R102-0612)




Network VP®/LTC 4.0 Radio Adapter Board

**SKU: R102-3125**

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.




## Network LTC™ 4.0



LEAD  
FREE

Network LTC 3.0/4.0 Surge Board *(Surge & Switch)*

**SKU: R102-8080**



Network LTC 3.0/4.0 Surge Board *(Surge & Switch)*

**SKU: R89-8521**



LEAD  
FREE

Network LTC 3.0/4.0 Pump & Comm Surge

**SKU: R102-8086** *(Same as R89-8589)*



Network LTC 3.0/4.0 Pump & Common Surge

**SKU: R89-8589**



LEAD  
FREE

Network LTC 3.0/4.0 Pump & Common Surge

**SKU: R118-1524** *(Same as R102-8086)*



Network LTC 4.0/Plus Timing Mechanism

**R102-0238**

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.



## Network LTC™ 4.0



LEAD  
FREE

**Network VP®/LTC 4.0 Radio Adapter Board**

**SKU: R102-8277** *(Same as R102-3125)*



**Network LTC 4.0/Plus Maxon Data Radio**

**SKU: R363-4638**



LEAD  
FREE

**Network LTC 4.0/Plus Output Module**

**SKU: R102-8084**

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.




## Network LTC™ Pro



Network LTC Pro VP-LTCP Timing Mechanism

**SKU: R118-4837**



Network LTC Pro Vehicle Power Distribution Board


**SKU: R118-2737**

## TDC 2-Wire System




TDC 2-Wire Decoder Timing Mechanism Assembly

**SKU: R118-3106**



TDC 2-Wire Decoder Mother Board, DC

**SKU: R118-0582** *(Works w/ R118-0584 DB)*



TDC 2-Wire Decoder Daughter Board, DC

**SKU: R118-0584** *(Works w/ R118-0582 MB)*

## VT 4



VT 4 Timing Mechanism

**SKU: R35-6220** – *\*Repair & Return Only*

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.





## Network 8000




Network 8000 Timing Mechanism

**SKU: R91-1280**




Network 8000 Power Supply

**SKU: R35-6166**




Network 8000 Surge Board

**SKU: R35-7899**



Network 8000 Triac Board

**SKU: R89-8100**



Network 8000 Power Supply

**SKU: R35-6326** – *\*Repair & Return Only*



Network 8000 Valve Board

**SKU: R35-8502** – *\*Repair & Return Only*

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.



## Modems



**Network 8000 Modem Board**

**SKU: R35-8646**



**LTC 2.0 Standard Modem**

**SKU: R89-7519**



**Standard Modem**

**SKU: R102-0104** (Works w/Network VP®) – **\*Repair & Return Only**



**Standard Modem**

**SKU: R102-8568** (Works w/Network VP) – **\*Repair & Return Only**

**LEAD  
FREE**



**Universal Modem - New Version**

**SKU: R102-0106** – **\*Repair & Return Only**



**Standard Modem - New Version**

**SKU: R118-6161** – **\*Repair & Return Only**

**LEAD  
FREE**



**Universal Modem**

**SKU: R102-8570** (Works w/Network VP)

**LEAD  
FREE**

**\*Subject to repair chargeback:** Warranty replacement does not cover surge or water damage. Boards sent in under warranty that, upon Toro inspection, are found to have water or surge damage, will be deemed ineligible and billed back to the customer for full board replacement cost. The faulty board will qualify for core credit.